

Fig. 7.34.




Fig. 7.35. Constant Torque
Three phase squirrel cage motor connection
arrangement for 2 speed one winding connection
for constant torque.




Fig. 7.36. Variable Torque
Three phase two speedsquirrel cage connection
arrangement for variable torque one stator winding




Fig. 7.37. 2 Speed induction motor control using INO + INC Push

operating

of the speed at which the motor is running.




Fig. 7.38.

Control using INO + INC push button. Change-over from fast to




Fig. 7.39.




Fig. 7. 40. Automatic Two speed Motor Control. The three phase induction motor stator is wound for single winding two speed for constant horse power and constant torque.